

**DASSAULT FALCON 900 s/n 030**  
Year 1988



***Bizjet SA, Geneva***  
***is pleased to offer the aircraft for sale***

**Airframe Total Time (AFTT): 14151**  
**Total Landings: 10473**

As of September 2011

**Avionics**

---

- FLT DIR EDZ-800S/820 Honeywell with MFD
- A/P SPZ 8000 Honeywell
- VHF Triple Collins VHF-22D
- ADF Dual Collins ADF 60B
- DME Dual Collins DME 42
- PDR Dual Collins TDR 94D (EHS)
- RAD ALT Dual RT-300 Honeywell
- FDR Sundstrand DXUS
- FMS Dual Honeywell NZ 2000
- VOR/ILS Dual Collins VIR-32
- HF Dual HF King-Bendix
- SATCOM Honeywell MCS 4000+ with CM250
- INS Triple Honeywell IRS - Laserf II
- RADAR Honeywell Primus 800
- CVR Fairchild A100A
- EGPWS Honeywell MK-5
- GPS Dual Honeywell HG-2021
- ADC Dual Honeywell AZ 810
- TCAS Honeywell 2000
- ELT ELTA ADT-406 Three Frequency

**Engines and APU**

---

**Engines:** Allied Signal Aerospace TFE 731-5AR-1C Thrust Reversers

Engine #	s/n	TSN	CSN	Time to CZI	Time to MPI
Engine #1	s/n P97326	11219	9716	3526	1426
Engine #2	s/n P97141	13289	9565	1767	1643
Engine #3	s/n P97214	14272	11969	2933	833

**APU:** Allied Signal Aerospace GTCP36-150(F) 8344 TSN

**Features**

---

ELS/EHS Transponder Regulation compliant; Teledyne AoA; Airshow 400; Lasertrak; CD/DVD Player; B-RNAV; RVSM, NAT-MNPS & CAT II compliant.

**Interior**

---

Partially renewed in June 2011; Beige leather with beige carpet; Fwd cabin section with one executive chair & one two-place sofa; Mid-cabin section with four executive chairs with a tables; Aft-cabin section with two three-place sofa (certified for four-places); Aft & Fwd Lav;

**Exterior**

---

Overall white; Repainted in June 2011.

### ***Maintenance***

---

No MSP Engine Program (Service Bulletin following MSP standard, Engine under Jet-Care Program). A,2A,3A,A+,2A+,3A+,4A+ check c/w 06-2011; B,2B,3B check c/w 03-2010; 4B check c/w 11-2004; 4C check c/w 06-2011; Landing Gear overhauled 08-2010; Maintenance performed under Public Transport rules; JAR OPS 1 compliant; No relevant damages comply with the a/c life; Aircraft enrolled in the new Maintenance Program (SB F900-390) – Extension of “A” & “B” Inspection Interval.

### ***Photos***

---











*Aircraft specifications subject to verification upon inspection  
Aircraft subject to prior sale or withdrawal from the market*